











instruction





1027 05 13 42
211/2



instruction



1027 05 13 42
211/2






++++ = MAX. 720°

++++ = MAX. 720°








instruction





1027 05 16 53
308/2


M10

M12




H+











1





2



3





+ = 180°



++ = 360°

MAX. +++ + 720°



instruction

1027 05 13 42

1027 05 16 53
308/2